

## Guide to Plastic Extrusion Design and Tooling

Plastic Extrusion is a high-volume manufacturing process, known for producing continuous, uniform plastic products. A key factor in its success is the design and tooling involved in shaping raw plastic into finished products. In this guide, we will explore the principles of plastic extrusion design and tooling, offering insights into how manufacturers create efficient, high-quality extrusion processes.

This process starts by feeding plastic material (pellets, granules, flakes, or powders) from a hopper into the barrel of the extruder. The material is gradually melted by the mechanical energy generated by turning screws and by heaters arranged along the barrel. The molten polymer is then forced into a die, which shapes the polymer into a shape that hardens during cooling.

### 1. What is Plastic Extrusion Design?



Plastic Extrusion Design refers to the planning and engineering of the shape, size, and structure of the plastic product to be manufactured through extrusion. This process involves creating a design that can be accurately produced using the extrusion die and other tooling components. The design determines the product's cross-sectional profile, ensuring it meets the required specifications for its intended application.

Extrusion design is essential because it directly impacts the quality, functionality, and manufacturability of the plastic product. Whether you are designing simple tubes, complex profiles, or multi-layered structures, getting the design right is critical for a successful extrusion process.

## 2. Understanding Plastic Extrusion Tooling

Plastic Extrusion tooling refers to the tools and equipment used to shape molten plastic as it moves through the extruder. The most important component of this tooling is the **extrusion die**, which dictates the final shape of the product. Tooling also includes other critical components like calibrators, cooling tanks, and cutters that ensure the product maintains its shape and size after exiting the die.









The precision of the extrusion tooling determines the dimensional accuracy, surface finish, and overall quality of the extruded plastic products. Proper tooling design allows for seamless and efficient production, reducing material waste and ensuring consistency.



### 3. Key Considerations in Plastic Extrusion Design


Designing plastic extrusion requires careful consideration of several factors that affect both the product's performance and the efficiency of the manufacturing process. Here are some key elements:

#### A. Wall Thickness / Hollow Sections / Radius considerations:

Even Wall Thickness		
Good Design	Poor Design	
		Profiles need an even wall thickness throughout. Large differences can cause unequal material flow through the tool which distorts the profile. Material will also cool at different rates, causing bowing of the finished extrusion.
Avoid Detail in Hollow Section		
Good Design	Poor Design	
		Hollow extrusions (tubes) are made using a vacuum former. Internal detail should be kept to a minimum since it is difficult to control during production. Complex detail can be achieved if the profile is opened up, no longer requiring the vacuum. Hollows within hollows should be avoided.
		
Radius		
Good Design	Poor Design	
		Radii should be as large as possible. Inside radii should be a minimum of .010" and outside corners should be no less than .020" to eliminate the possibility of notching and cracking in the corners.

## B. Material Selection

The type of plastic used (e.g., PVC, PE, PP, ABS, PC) plays a significant role in the design process. Different plastic materials have varying melt flow rates, which influence the product's behavior during extrusion and cooling.



## C. Cooling and Shrinkage

Extruded products undergo shrinkage as they cool. Designers must account for this by adjusting the dimensions in the design phase to ensure that the final product meets specifications after cooling.

## 4. Types of Extrusion Dies and Tooling

There are several types of extrusion dies and tooling setups that manufacturers use, each suited to specific applications:



### A. Flat Die

Flat dies are used to produce plastic sheets and films. The molten plastic is spread across a wide surface, and the thickness of the sheet is controlled by adjusting the die gap.

### B. Round Die

Round dies are ideal for creating tubular or cylindrical products like pipes and hoses. These dies have circular openings that shape the plastic into the desired cross-section.

### C. Profile Die

Profile dies are custom-made to create specific, often complex cross-sectional shapes. These dies are used in applications like window frames, seals, or custom plastic profiles.

### D. Co-extrusion Die

In co-extrusion, multiple layers of different materials are extruded simultaneously through a specialized designed die. This allows manufacturers to combine properties like strength, flexibility, or barrier performance into a single product.

## 5. Common Materials Used in Plastic Extrusion Tooling

The materials used in the construction of extrusion dies and tooling must withstand the high temperatures and pressures of the extrusion process. Common materials include:

- **Tool Steel:** Known for its strength and heat resistance, tool steel is a popular choice for die construction.
- **Stainless Steel:** Corrosion-resistant and durable, stainless steel is often used in food or medical-grade extrusion processes.

These materials help maintain die accuracy, reduce wear, and prolong the lifespan of the tooling, contributing to cost-effective production.

## 6. Challenges in Plastic Extrusion Design and Tooling

Several challenges may arise during plastic extrusion design and tooling, including:

- **Flow Imbalances:** Inconsistent material flow through the die can lead to uneven product surfaces or thickness variations. Proper die design and testing are critical to address this.
- **Die Wear:** Continuous use of extrusion dies can lead to wear, which affects the precision of the final product. Regular maintenance and material selection can minimize this issue.
- **Heat Management:** Controlling the heat during extrusion is crucial to ensure the material flows smoothly through the die. Poor heat management can cause issues like melt fracture or surface imperfections.

## Conclusion

Extrusion profile design and tooling are essential components of the manufacturing process, determining the quality and efficiency of the final product. By carefully considering factors like material selection, die design, and modern CAD tools, manufacturers can create high-performance products while reducing costs and improving sustainability. As technology advances, ongoing innovations in design and tooling will drive further advancements in the plastic extrusion industry.